

# ANNUAL SURVEYS.

15978

No. 365 on the Dry "Comet" Survey held at London Date 27 April 1850  
 Tonnage 260 Built at New Haven Master Air M  
 By whom built Gray Owners Reid & Co  
 Port belonging to London Destined Voyage Madeira  
 If Surveyed Afloat or in Dry Dock in Williams Dock

Last Survey, No. 15639 Port of London Classed 12 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y M</u> When put on <u>Apr</u>	Standing & Running Rigging
Plank (Bottom) and Counter	1850	

General Observations and Opinion,

at present bottom stripped Caulked from the Keel to the waterways and bottom resheathed with yellow metal on paper the quarter badges removed and

Committee Minute 7th May 1850 not replaced as in most efficient  
 Character assigned 12 A 1 Condition May require as Clap  
111 111 111 111 111 111 111 111 111 111  
 Certificate (if required)

No. 335 on the Dry "Elizabeth" Survey held at London Date 23 April 1850  
 Tonnage 285 Built at Sarbro Master Burton  
 By whom built Smith & Co Owners Smith & Co  
 Port belonging to Sarbro Destined Voyage Triste  
 If Surveyed Afloat or in Dry Dock in Globe Dock

Last Survey, No. 14767 Port of London Classed 1847 Coal 4 1/2 A 1

The present Condition of the

Decks	Treenails <u>overhauled at belgs</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling <u>repaired</u>	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y M</u> When put on <u>Apr</u>	Standing & Running Rigging
Plank (Bottom) and Counter	1850	

General Observations and Opinion,

at present bottom stripped Caulked to the keel and resheathed with yellow metal on felt - Ceiling repaired in spots on both belgs and flat - New head

Committee Minute 7th May 1850 tails fitted as in efficient  
 Character assigned 12 A 1 Condition May require as Clap  
111 111 111 111 111 111 111 111 111 111  
 Certificate (if required)