

Continuation

16124

Port

Classed

REPAIRS at present from damage new after hood of Carboard
Sheerstrake three new after rough tree transoms
and after length of rail and half seat transoms
& knee on the same side also new ^{Harpoon} side counter
timber - Sheerstrakes & timberheads & quarter bulkhead
wales topsides and Sheerstrakes scraped bright and
bolts and brunnails driven out for survey and found
sound and good and the planks three which they ^{top}
the deck and coming the plank sheer waterways &
beams, the house timbers, knightheads, breasthooks and
transoms the floors and pulson the ceiling & frame
and inner surface of the outside blue ring where seen
are sound & good & the sheer & general form unaltered

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons *transverse over*

Clamps and Shelves

Ceiling

Rudder

Copper Ym When put on 1847

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

<i>Anchors</i>	<i>No. of</i>
----------------	---------------

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

The Amount of Fee.....£ 2 : — : — is received by me,

Special..... 3 : 3 : —

Certificate (if required) _____:_____:

Committee's Minute *9th July* 18*50*

Character assigned

for the longest period
Prescribed by the Rules
Say from 1849. 4th A1

Q. B. Fitchie

Fourteen

1890

LOW 628-0 43