

# REPORT of SURVEY for REPAIRS.

Change of Owners.

No. 866 Survey held at London Date Feb: 14<sup>th</sup> to Feb: 15<sup>th</sup> 1851  
 on the Athenian B<sup>t</sup> Master Deighton Geo: Case  
 Tonnage 513 Built at Sunderland When built 1842  
 By whom built \_\_\_\_\_ Owners Teigne & Co  
 Port belonging to London Destined Voyage Bermuda  
 If Surveyed Afloat or in Dry Dock In Union Dock & Afloat

Last Survey, No. 15734 Port London Classed 10 A 1

## REPAIRS

The hull has been opened for the inspection of the Gov<sup>r</sup> Surveyors and found good - The yellow metal has been patched, and the lower deck caulked all over for the reception of troops - The vessel has been caulked from the bottom up and over all to the watertight seam

## Present Condition of the

Decks <u>good</u>	Treenails <u>apparently good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>caulked good</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>"</u>
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good &amp; firm</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>part decayed &amp; forced good</u>	Sails <u>"</u>
Planksheers <u>caulked good</u>	Clamp and Shelves <u>good</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>good</u>	Cables <u>good &amp; sufficient</u>
Topsides <u>"</u>	Rudder <u>examined</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>1/4" 1/2" F</u> When put on <u>1850</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>good &amp; same as</u>		

## General Observations and Opinion,

This vessel is in good condition and fit to remain as at present  
claped

The Amount of Fee.....£ 3 : 0 : 0 is received by me, Augustus B. Cross

Special.....

Certificate (if required) .....

Committee's Minute 25<sup>th</sup> Feb 1851

Character assigned 10 A 1



© 2019

Lloyd's Register  
Foundation

LOV629-0469