

REPORT of SURVEY for REPAIRS.

Continuation

No. 644 Survey held at Sondon Date 24th & 25th Mar 1851
 on the Bark "Conservative" Master D. Waterston
 Tonnage 345 Built at Sunderland When built 1840
 By whom built Owners Blythe & Co
 Port belonging to Sondon Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock in West India & M^{rs} Youngs Dock

Last Survey, No. 15174 Classed A, 1

Port Sondon

REPAIRS

at Sondon, Wales, topsides and sheerstrakes scraped
bright and botts and treennails driven out for survy
 and all the requisites of Rules Section 54 Completed
 with one plank of topsides renewed on each side
 the throat botts of the upper deck stems having
been found wasted have been renewed of iron
 the treennails and timbers exposed found sound
& good — The upper deck & comings, the outer
planks and ceiling the plank sheers waterways
and beams the house timbers knights heads
breasthooks and transoms the floor & elson
P. Lowe

Present Condition of the

Decks <u>New in 1850</u> <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u> </u>	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings <u> </u>	Keelsons <u> </u>	Sails <u>Do</u>
Plank sheers <u> </u>	Clamps and Shelves <u> </u>	Anchors No. of <u>Do</u>
Sheerstrakes <u>Scraped</u>	Ceiling <u> </u>	Cables <u>Do</u>
Topsides <u>Bright</u>	Rudder <u> </u>	Hawsers and Warps <u>Do</u>
Wales <u> </u>	Copper <u>Y Metal in 1849</u>	Standing & Running Rigging <u>Do</u>
Plank (Bottom) and Counter <u> </u>	<u>repaired now</u>	

General Observations and Opinion,

This Vessel is in efficient Condition
and in our opinion fit to be Continued in the
first Class for the longest period prescribed by

The Amount of Fee £ 4 : - : - is received by me, the Rules say from
Special 23 & 3 1850. 3 yrs 11
 Certificate (if required) 10

Committee's Minute 1st April 1851

Character assigned Mr P. A. 1 yr 3 yrs 4

1668 & Son

The frame & inner surface of the outside
planking where Sea are found exposed
and the sheer & general form unaltered

J. H. H. H.
J. H. H. H.



© 2019

Lloyd's Register
Foundation