

# ANNUAL SURVEYS.

16909

No. 176 Survey held at London Date 18 June 1851  
 on the Ship "Viscount Dundee" Master   
 Tonnage 514 Built at Liverpool When built 1842  
 By whom built  Owners Taylor & Co  
 Port belonging to Liverpool Destined Voyage Canton  
 If Surveyed Afloat or in Dry Dock in Messrs Young & Co Dock

Last Survey, No. 15945 Port of London Classed 12 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>yes</u> When put on <u>1850</u>	Standing & Running Rigging

General Observations and Opinion,

at Present Docked to inspect the State of Metal Sheathing which was found smooth & good. It is efficient Condition and fit to remain as Clipped

Committee Minute 11 July 1851

Character assigned 12 A 1

Certificate (if required)

No. 382 Survey held at London Date 20 June 1851  
 on the Ship "George Pollock" Master Wilkes  
 Tonnage 630 Built at Moulmein When built 1847  
 By whom built  Owners Suscombe  
 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock in Mr Carters Dock

Last Survey, No. 15514 Port of London Classed 12 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>yes</u> When put on <u>1857</u>	Standing & Running Rigging

General Observations and Opinion,

at Present bottom stripped of Copper only and sheathed with yellow metal on the old wood

Committee Minute 11 July 1851

Character assigned 12 A 1

Certificate (if required)