

Change of Owners & Closing Asterisk

Dec 18 Dec

REPAIRS at present Wales topsides and sheer strakes scraped bright and bolts and trenails driven out for Surveys in accordance with Sect^o 60 and found Sound & good with exception of part of the iron bolts which have been renewed where necessary - about 500 feet of the upper deck renewed of Red Pine beams exposed Sound & good - the bottom ^{stuffed} Caulked and sheathed with yellow metal on paper - the upper deck & Comings the outside and Ceiling Planks the Plank sheer waterways and beams the main timbers, Rightheads, breasthooks and transoms the floors & Kelsons and the flame & inner

General Observations and Opinion,

The Amount of Fee...../£ — : 10 : / is received by me,

Certificate (if required) : 5 : —

Character assigned

Character assigned 111 Yankee

LON 631-0188