

REPORT of SURVEY for REPAIRS.

17395

No. 420 Survey held at London Date March 4th 1852
 on the By Unity Master F Morrison
 Tonnage 262 Built at Sunderland When built 1845
 By whom built _____ Owners Gosley
 Port belonging to Sunderland Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Dowson's Dock

Last Survey, No. 10070 Port London Classed 8 A1

REPAIRS From damage, Yellow Metal stripped, hung in shores, & caulked from the keel to the waterways, two new deck beams, three new lodging knees, stem post additionally bolted rudder braces refastened, windlass & camels bolt chocks refitted, started keeneails removed, new head rails & battening, three new rough tree stanchions several throat bolts of the hanging knees replaced & sheathed with Yellow Metal on felt

Present Condition of the

Decks	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson <u>Do</u>	Pumps <u>Do</u>
Comings	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower Stm & Kedge</u>
Sheerstrakes	Ceiling <u>Do</u>	Cables <u>well found</u>
Topsides	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales	Copper <u>Yellow Metal</u> When put on <u>1852</u>	Standing & Running Rigging <u>good found</u>
Plank (Bottom) and Counter		

General Observations and Opinion This vessel is in a very good condition to continue as classed

A. M. Dole,

The Amount of Fee.....£ 1 : : is received by me,

Special..... 3 : 3 : 0 Damage

Certificate (if required) : :

Committee's Minute 23rd March 1852

Character assigned S. T. 1



© 2019

Lloyd's Register
Foundation

LON631-0353