

REPORT of SURVEY for REPAIRS.

17407

Rec 23 Mar

Change of Owners
 No. 331 Survey held at London Date March 24 1852
 on the Bk Durango Master R Garbutt
 Tonnage 301 Built at New Brunswick When built 1841
 By whom built _____ Owners T Hopper
 Port belonging to London Destined Voyage Bremen & New York
 If Surveyed Afloat or in Dry Dock Commercial Dock

Last Survey, No. 15820 Port London 1050 SS 4 yrs Classed AE 1
 REPAIRS Waterways & stations caulked

Present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan <u>good</u>
Waterways <u>Do</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings <u>Do</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>Good</u>	Sails <u>well frayed</u>
Planksheers _____	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower's Stm & Wedge</u>
Sheerstrakes _____	Ceiling <u>Do</u>	Cables <u>well frayed</u>
Topsides <u>very</u>	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales <u>fair condition</u>	Copper <u>light marks</u> When put on <u>1851</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion, I am of opinion from the good appearance this vessel is in good condition for the safe conveyance of dry and perishable cargoes and may continue as classed

The Amount of Fee.....£ 2 : : is received by me, R. Middleton
 Special..... : :
 Certificate (if required) : :

Committee's Minute 26th March 1852
 Character assigned AE 1



© 2019

Lloyd's Register
 Foundation
 LON 631-0365