

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 222 Survey held at London Date May 8th 1852
 on the Bk Leonard Dobbin Master J. B. Agar
 Tonnage 611 Built at Quebec When built 1837
 By whom built _____ Owners W. Wilkinson & Co
 Port belonging to Whitby Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 14058 Port London S & S 103 Classed A, 1

REPAIRS One pair of Iron hanging knees to the deck beam, one pair to the
hull beam, both in midships, upper works caulked & the ceiling
repaired,

Present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>Do</u>	Breasthooks and Stemson	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>where</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings <u>Do</u>	Timbers of the Frame <u>seen</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons	Sails <u>well found</u>
Planksheers	Clamps and Shelves <u>Good</u>	Anchors No. of <u>3 Bowers Stm & Kedge</u>
Sheerstrakes <u>Good</u>	Ceiling <u>Do</u>	Cables <u>well found</u>
Topsides <u>Good</u>	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales	Copper <u>YH</u> When put on <u>1840</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion, We are of opinion this vessel is in a good & efficient state
for the safe conveyance of dry & perishable cargoes &
may continue as classed

The Amount of Fee.....£ 3 : — : — is received by me,

Extra attendance Special..... 1 : 1 : 0

Certificate (if required) : 10 : —

Committee's Minute 25 May 18 52

Character assigned A, 1

W. H. W. W. W.
J. H. R. R. R.