

REPORT of SURVEY for REPAIRS.

17585

No. Survey held at London Date June 5th to 12th 1852
 on the Ship "Crystal Palace" Master Narracott
 Tonnage 480 Built at Teignmouth When built May 1852
 By whom built Mansfield & Son Owners Mr Lidgett
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock In Snook's Dry Dock

Last Survey, No. 500 Port Teignmouth Classed 11 A 1
 5 mo 52

REPAIRS now done of damage sustained by being on shore near
Teignmouth in her passage to London. More of particulars in Special
Report.

56 Feet of False Keel new, Ship hung in Shaws,
and the Bottom Caulked, also three broken Warps
replaced.

Not of Accident. The Bottom Sheathed with Yellow
Metal or Paper

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good</u>	Pumps
Comings } <u>good</u>	Transoms, Pointers, and Crutches } <u>good</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings } <u>d^g</u>	Keelsons <u>d^g</u>	Sails <u>and sufficient</u>
Plank sheers	Clamps and Shelves <u>d^g</u>	Anchors No. of
Sheerstrakes <u>d^g</u>	Ceiling <u>d^g</u>	Cables
Topsides <u>d^g</u>	Rudder <u>d^g</u>	Hawsers and Warps
Wales <u>d^g</u>	Copper <u>Metal</u> } When put on <u>new new</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^g</u>		

General Observations and Opinion,

This Ship is now in good condition, eligible to remain
as classed A 1

The Amount of Fee.....£..... is received by me,

Special..... : : La Martin

Certificate (if required) : : W. Martin

Committee's Minute 22 June 1852

Character assigned 11 A 1

Special Report } £2-2-0
on damage



© 2019

Lloyd's Register
Foundation

LON 632-0035