

17592

Dec 24 1894

The present Condition of the

Windlass and Capstan Good
Pumps —
Boats two
Masts, Yards, &c. Sufficient
Sails Do
Anchors No. of 2. 1. 1
Cables Sufficient
8. 6. 4
Hawsers and Warps Do
Standing & Running Rigging Do

General Observations and Opinion,

Certificate (if required)



The present Condition of the

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Sails
Anchors No. of
Cables
Hawsers and Warps
Standing & Running Rigging

General Observations and Opinion,

Character assigned

SEYFANG AND CO. PRINTERS, 57, FARRINGDON STREET, LONDON.

LON 632-0042

Certificate (if required)

Lloyd's Register
(if required)
Foundation