

REPORT of SURVEY for REPAIRS.

Continuation Change of Owners

No. 257

Survey held at

London

Date 23 Nov till 3 Dec 1852

on the

Ship "Simandra"

Master

H. Smith

Tonnage

382
432

Built at

Little Hampton

When built

1841

By whom built

Owners

Barnett

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock

in Young & Co. Dock

Last Survey, No.

15967

Port

London

Classed

11 A 1

REPAIRS

at present wales topsides and sheerstrakes scraped bright one length of sheerstrake new on the larboard side treenails good all the in & out bolts of the lower deck new renewed of iron - two new midship lengths of keelson and stem son new also new new lower breast hook of iron - bottom stripped caulked and resheathed with yellow metal on felt - The deck & Comings the outside & ceiling planks the plank sheers waterways and beams the house timbers height - heads breasthooks and transoms the floors keelsons the frame & inner surface of the outside planks. Where new are square & good

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plank sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

lower one new

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

1852

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

This vessel is in efficient Condition and all the requirements of Rules Sect 54 has been complied with & she is eligible in our opinion

The Amount of Fee.....£ 4 : - : - is received by me,

Special..... 3 : 3 : -

Certificate (if required) : 10 : -

Committee's Minute

31st Dec^r 1852

Character assigned

11 A 1 Cont 4 A 1

LON 632-0386

Lloyd's Register Foundation