

18031

REPORT of SURVEY for REPAIRS.

No.

Survey held at

London

Date 1st 5th 8th 29th Jan^y 1853

on the

Bⁿ "Kath Stewart Forbes" Master

W Wright

Tonnage

457

Built at

Northfleet

When built

1818

By whom built

W^m Pitcher

Owners

Chapman

Port belonging to

London

Destined Voyage

Sydney

If Surveyed Afloat or in Dry Dock

in M^r Pitcher's Dock & Afloat

Last Survey, No.

17117

Port

London

Classed

* A 1

REPAIRS

at present part of the topgallant forecattle plank removed, and three new top timbers fitted and foreheads of the topgallant birkney reviewed - the rails and fittings of head refastened - the wabs and top plates Caulked, and yellow metal sheathing repaired generally overhauled in hull & stores

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plank sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

1857

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good

Good

will

found

sufficient

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required)

Committee's Minute

15th Feb^y 1853

Character assigned

A 1

astorick

J. Pitcher
 J. R. Pitcher
 Lloyd's Register
 Foundation