

REPORT of SURVEY for REPAIRS.

No. 283 on the Ship Herefordshire Master G Richardson
 Tonnage 1355 Built at Bombay When built 1855
 By whom built J. J. J. J. Owners J. J. J. J.
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Somes dry dock.

Last Survey, No 17340 Port London Classed A 1
 REPAIRS N 4 9. 42.

At present, two new paulbitts, two new carriage bitts, new windlass. Oak shute for cable chain to lead fair from the windlass to hawse pipes on lower deck two hanging knees to Orlop deck beams, wales, topsides, sheershakes, and plankishers cantbed, head knee rebolted also hawse pipes rebolted. The deck new in the wake of windlass & under the forecath.

Present Condition of the

Decks	good	Treenails		Windlass and Capstan	good
Waterways	do	Breasthooks and Stenson	good	Pumps	do
Cowings	do	Transoms, Pointers, and Crutches	do	Boats	5 he do
Upper Deck Beams & Fastenings	do	Timbers of the Frame	wherever	Masts, Yards, &c.	do
Lower Deck Beams & Fastenings	do	Keelsons	do	Sails	do
Plankishers	do	Clamps and Shells	do	Anchors No. of	3 B 18 1 K do
Sheerstrakes	do	Ceiling	do	Cables	do
Topsides	do	Rudder	do	Hawsers and Warps	do
Wales	do	Copper	do	Standing & Running Rigging	do
Plank (Bottom) and Counter	do	When put on	1851		

General Observations and Opinion, This vessel is in efficient condition and in an opinion, fit to carry dry and perishable cargo to and from all parts of the world, and may remain in service.

The Amount of Fee.....£ 3 : - : is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 10 : -

Committee's Minute 11th Oct 53

Character assigned R. 1

Special £1. 1

records report

LONDON-0476