

# REPORT of SURVEY for REPAIRS.

18433

No. 418 Survey held at London Date 28th March 1854  
 on the Barge, "Rubicon" Master C. Vaux  
 Tonnage 126 Built at Sunderland When built 1851  
 By whom built \_\_\_\_\_ Owners Thomson  
 Port belonging to Sunderland Destined Voyage Govt Service  
 If Surveyed Afloat or in Dry Dock Young Son & Co's Dock

Last Survey, No. 4563 Port Sunderland Classed S A 1

## REPAIRS

At the present time partly for damages from Collision, particulars in Special Report.  
 part new Rails, new Bowsprit and part Topgallant Bulwarks  
 The yellow Metal sheathing stripped of the bottom and caulked from keel upwards including Decks, The bottom Resheathed with yellow Metal over Felt

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y Metal</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, This ship appears to be in good condition at the present time and eligible to remain as classed

The Amount of Fee.....£ : : is received by me, M. M. Intyre  
 Special..... 2 : 2 : -

Certificate (if required) : :

Committee's Minute 21st April 1854

Character assigned S A 1

Sp Damage £212- 11 12



© 2019

Lloyd's Register Foundation

LON 634-0350