

# ANNUAL SURVEYS.

19789

No. 494 Survey held at London Date Feb 6 to 20 1854  
 on the Brig "Ellen" Master S. C. Paddon  
 Tonnage 175 Built at Rye When built 1847  
 By whom built \_\_\_\_\_ Owners Griffiths  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock William's Ways & Dock

Last Survey, No. 17825 Port of London Classed 12 A 1  
 52

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper on paper</u> When put on <u>1854</u>	

General Observations and Opinion, Now done, the Yellow Metal sheathing renewed on paper, bottom Caulked - She appeared in good and efficient Condition, fit in our opinion to remain

Committee's Minute 18th Decy 1855

Character assigned 12 A 1

as classed A 1

B. Wainwright  
J. H. Ritchie  
 Certificate (if required)

No. 166 Survey held at London Date June 1855  
 on the Ship "African" Master J. Pollock  
 Tonnage 750 Built at Sunderland When built 1833  
 By whom built \_\_\_\_\_ Owners Gregg  
 Port belonging to Belfast Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 5567 Port of Sunderland Classed 13 A 1  
 53

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper on Felt &amp; paper</u> When put on <u>Now new</u>	

General Observations and Opinion, Now done the Yellow Metal sheathing stripped, all the outside planking Caulked, bottom sheathed with Yellow Metal on Felt the upper course, and from there to the keel on paper. She appears to be in good Condition, fit in my opinion

Committee's Minute 10th Decy 1855

Character assigned 13 A 1

to remain as classed A 1

B. Wainwright  
 Certificate (if required)