

REPORT of SURVEY for REPAIRS.

No. 76 Survey held at London Date 31st Oct^r 1855
 On the S^r Helia Master J Brown
 Tonnage 127 Built at London When built 1844
 By whom built _____ Owners Northcote &
 Port belonging to London Destined Voyage Mogador
 If Surveyed Afloat or in Dry Dock Youngs Dry Dock

Last Survey, No. 1821 B Port London Classed 11. A1

REPAIRS

at present of damage incurred by striking upon Margate sand while proceeding on her voyage from London to Mogador more of particulars in special report

Metal sheathing stripped off the post & a portion of the adjoining planking - the keel set up close to the heel of post & additionally bolted together the stowtail plates removed refitted & fastened - plank in deck connected with post set down where started & fastened finally rabbet & seems adjoining uncovered recaulted & the Metal sheathing when stripped replaced with new - Bower anchor stock (broken) repaired Not of damage 5 seems on each side above Metal sheathing recaulted

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>efficient</u>	Windlass and Capstan	<u>efficient</u>
Waterways		Breasthooks and Stemson		Pumps	<u>2</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>2</u>
Upper Deck Beams & Fastenings	} <u>Good & Firm</u>	Timbers of the Frame	} <u>where seen</u>	Masts, Yards, &c.	<u>2</u>
Lower Deck Beams & Fastenings		Keelsons		Sails	<u>well found</u>
Planksheers	} <u>Good order where seen</u>	Clamps and Shelves	} <u>seen</u>	Anchors	No. of <u>2 B 1 S 1 K</u>
Sheerstrakes		Ceiling		Cables	<u>13</u>
Topsides		Rudder		Hawsers and Warps	<u>well found</u>
Wales	} <u>seen</u>	Copper	<u>Yel Met</u>	When put on	<u>53</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Firm

This vessel is now in efficient condition & eligible to remain as classed A1.
 Thomas Alexander

The Amount of Fee.....£ : 10 : - is received by me,

Special..... 2 : 2 : -

Certificate (if required) : 2 : 6

Committee's Minute 16th October 1855

Character assigned 11 A1

Record Repair

Special fee £2.2
 & Report



© 2019

Lloyd's Register Foundation

LON636-0263