

REPORT of SURVEY for REPAIRS.

Change of owners

No. 5 Survey held at London Date Feb^y 7th 1857
 on the Y^h Abbot Master R. Hardy
 Tonnage 245 Built at Arbroath When built 1851
 By whom built _____ Owners Banner Brothers
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Bull head dry dock

Last Survey, No. 14142 Port London Classed G A 1

REPAIRS Now done; the yellow metal sheathing stripped the bottom recaulked from metal line to keel and resheathed with yellow metal on felt -

Present Condition of the

Decks	} Good	Treenails	} Good	Windlass and Capstan	} In good order and sufficient
Waterways		Breasthooks and Stemson		Pumps	
Comings	} do	Transoms, Pointers, and Crutches	} where seen	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} where seen	Keelsons	} do	Sails	
Planksheers		Clamps and Shells		Anchors No. of	
Sheerstrakes	} do	Ceiling	} do	Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} do	Copper <u>T M or F</u> When put on <u>now</u>	} do	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good and firm

This vessel is now in a good and efficient state and is eligible in our opinion to remain classed G A 1

The Amount of Fee.....£ 1 : : is received by me, H. B. Woods.

Special..... : :

Certificate (if required) : :

Committee's Minute 6th March 1857

Character assigned G A 1



© 2019

Lloyd's Register Foundation

LON 638-0097