

# REPORT of SURVEY for REPAIRS.

No. 240 Survey held at London Date 2<sup>nd</sup> March to 6<sup>th</sup> Mar 1857  
 on the Barque W<sup>m</sup> Bryan Master  
 Tonnage 312 Built at Southampton When built 1816  
 By whom built \_\_\_\_\_ Owners Thompson  
 Port belonging to Boole Destined Voyage Lon to  
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 20133 Port London Classed A. 1

## REPAIRS

S.S. 54.

1, 56

Saw this vessel in the West India Dock and met the Owner on board and examined her for an Annual Survey found the Waterway, Shelf, and Upper D<sup>th</sup> Clamp very rotten - left the following Notice Card - the owner intimating that he should take the ship home for repairs - that the rotten Waterway, Shelf & Clamp be renewed, 3 beams which are split and defective be scarfed and also the defective Hold Beam Waterway be renewed.

M<sup>r</sup> Thompson Owner  
 Ship W<sup>m</sup> Bryan

Signed { Edwin R Bouchman  
 W<sup>m</sup> Mumford

## Present Condition of the

On the 7<sup>th</sup> found the vessel had sailed 4<sup>th</sup> March 1857

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>defective</u>	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchor No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

## General Observations and Opinion,

## Caulking of Bottom, Deck, & Waterways.

We are of opinion that this vessel's character should be expunged until the above repairs are attended to

The Amount of Fee.....£ : : is received by me,

Special..... : : :

Certificate (if required) : : :

Committee's Minute 10<sup>th</sup> March 1857

Character assigned Expunged Character

See Lou W<sup>m</sup> 906 Notice to owner

L.D. dett 11/6/57

Edwin R Bouchman  
 W<sup>m</sup> Mumford