

REPORT of SURVEY for REPAIRS.

No. ³⁷⁸ Survey held at London Date 30th Aug. 1856
on the Ship "Plantagenet" Master
Tonnage 687 Built at Newcastle When built 1838
By whom built Messrs Smith Owners Watson & Co
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock in Messrs Young & Co dry dock

Recd 31/8/57
Clerk

Last Survey, No. 14700 Port London Classed 2nd A. 1 omitted
SS. 55 C 4 55

REPAIRS at this time the wales caulked and the yellow
metat sheathing patched, several bolts of the
lower deck binding renewed, the lower deck
caulked

Present Condition of the		
Decks <u>new in 1855 Good</u>	Treenails	Windlass and Capstan
Waterways <u>do</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame	Masts, Yards, &c. <u>well</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons	Sails <u>found</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>1</u>
Sheerstrakes	Ceiling	Cables <u>Sufficient</u>
Topsides <u>Good</u>	Rudder	Hawsers and Warps
Wales <u>caulked</u>	Copper <u>Ym</u> When put on <u>1855</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways.

This Vessel was omitted to be reported at the
proper time but when seen was in our
opinion fit for the safe conveyance of dry
and perishable cargoes
to & from all parts of the
world and capable
to the main classes of
with aspects
Hitcher

The Amount of Fee.....£..... is received by me,
Special..... : :
Certificate (if required) : :
Committee's Minute 1st September 185
Character assigned 2nd A. 1