

REPORT of SURVEY for REPAIRS.

21297

No. 632 on the Y3rd "Comet" Survey held at London Date 16th Jan^y 1857
 Master Partridge
 Tonnage 225 Built at Newhaven When built 1847
 By whom built _____ Owners J. Reid & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fountain Slipway

Last Survey, No. 15970 Port London Classed 12 A 1

REPAIRS In consequence of Damage; on the Port Bow 4 Rough tree^{54.} Timbers, the Cathead and bow Rails renewed for minor particulars see Special Report -

Recaulked from the metal line to the waterway seam

Present Condition of the

Decks	} Good	Treenails	} Good	Windlass and Capstan	} In good order
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Cruiches		Boats	
Upper Deck Beams & Fastenings	} Do	Timbers of the Frame	} where seen	Masts, Yards, &c.	} Sufficient
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} where seen	Ceiling	} Standing & Running Rigging	Cables	}
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>YM</u> When put on <u>1854</u>			
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good and firm.

This vessel is now in a good and efficient state and is eligible in our opinion to remain classed 12 A 1

The Amount of Fee.....£ _____ is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 15th September 1857

Character assigned 12 A 1 LD

Damage £2.2.0. paid 28/1/57



© 2019

Lloyd's Register Foundation

LON 638-0481