

21942

Edwards
Eras

If Surveyed Afloat or in Dry Dock *Some Dry Dock*

REPAIRS. Remarks:- At the request of the Owner
We surveyed this vessel's Yellow Metal sheathing
to ascertain its condition (For particulars see
Special Report)

On examination found the yellow metal sheathing very much worn and perforated, and in our opinion not fit to remain on for another voyage.

Now done: yellow metal sheathing stripped off and renewed upon felt.

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchor No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in good and efficient condition, and in our opinion eligible to remain

Certificate (if required) : :

Character assigned 13415 record

Charge Special £2. 2

Bill to Messrs. Vivian & Co. Coffee Merchants
14 Upper Thames Street
for request of Mr. Marshall 12 May 58

LON 639-0397