

REPORT of SURVEY for REPAIRS.

No. 21796 Survey held at London Date 26th Oct. to 7th Nov. 1857
 on the Ship Malabar Master J. Toft
 Tonnage 373 Built at Greenock When built 1835
 By whom built _____ Owners Wilson
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat West. I. Dock

Last Survey, No. _____ Port See Report annexed Classed 12th A. I.

REPAIRS of damage now done:— Knight-heads partly renewed, three sawse timbers, two long top timbers and three rough tree stantions on the Starboard Bow, also one fore hood of plank sheer, and five planks of fore castle drifts renewed, two fore hoods of sheerstrakes, three planks of topsides, and the ceiling to fore castle drifts

On the Port side the ceiling of drifts renewed from the cathead forward, and two timber heads.

Rough tree sail and two stantions renewed in way of fore rigging on the Starboard side, cheek and bobstay plate to knee of head refitted and bolted, and the vessel caulked from the metal line upwards on the Starboard Bow including the flat of topgallant fore castle deck

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Sides	When put on	Standing & Running Rigging
Bank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in good condition, where seen is the hold being full of Cargo (while repairing). Fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world, and in my opinion eligible to

Amount of Fee.....£ : : is received by me, remain as Classed 12th A. I.
 Special..... : :
 Certificate (if required) : :

Committee's Minute _____ 185

Character assigned See Report annexed

Special Attendance £ 2.2.0

H. J. Boulds.



© 2019

Lloyd's Register Foundation

LON 639-0452