

21851

REPORT of SURVEY for REPAIRS.

No. 301 Survey held at London Date 11th June to 6th July 1858
on the Ship "Plantagenet" Master S. Ashfield
Tonnage 687 Built at Newcastle When built 1838
By whom built 806 Owners Watson & Co
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Afloat in the Victoria & E.D. Docks & Mr. Young & Co's dry dock

Last Survey, No. 21270 Port London Classed *A, 1 S S 55
C 4 56

REPAIRS

A good many sheets of Yellow Metal stripped off on each side below deck and about 100 Treennails in way thereof renewed with English Oak. Arms of Standards on Store Beams rebolted, the caulking of bottom where exposed made good, and recaulked from Yellow Metal line to waterway beam, the caulking tried and found satisfactory - remetalled where stripped over feet

Present Condition of the

Decks	Good	Treenails	Some renewed	Good	Windlass and Capstan	Good
Waterways	do	Breasthooks and Stemson	do	do	Pumps	2 of Iron do
Comings	do	Transoms, Pointers, and Crutches	do	do	Boats	four do
Upper Deck Beams & Fastenings	do	Timbers of the Frame	do	where seen	Masts, Yards, &c.	In good
Lower Deck Beams & Fastenings	do	Keelsons	do	Good	Sails	
Planksheers	Good	Clamps and Shelves	do	do	Anchors No. of	
Sheerstrakes		Ceiling	do	do	Cables	order and
Topsides		Rudder	do	do	Hawsers and Warps	
Wales	where	Yellow metal on keels	do	do	Standing & Running Rigging	sufficient
Plank (Bottom) and Counter	seen	Copper	When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This vessel appears to be in good condition and fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world we are therefore of opinion she may continue as Classed *A, 1

The Amount of Fee.....£ : : is received by me,

Special..... 2 : 2 :

Certificate (if required) : 5 :

Committee's Minute 13th July 1858

Character assigned *A, 1 asterisk

Will^m C. Dacey
J. C. Martin

