

21965

REPORT of SURVEY for REPAIRS.

No. 14 Survey held at London Date Sept 26th 1858
on the Barge "Madras" Master J. Davis
Tonnage 331 Built at Whitehaven When built 1827
By whom built _____ Owners J. Hilbery
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock West-India Dock

Recd. 6 Sept 58
Capt

Last Survey, No. 21335 Port London Classed A. 1.

REPAIRS

Now done, Caulked from the Metal sheathing
up, including the upper deck, two hold beams in
Midships, and one beam End renewed with
African Aulc.

Present Condition of the

Decks <u>Caulked</u>	Treenails _____	Windlass and Capstan _____
Waterways <u>Caulked</u>	Breasthooks and Stemson _____	Pumps _____
Comings <u>Caulked</u>	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings } <u>from</u>	Timbers of the Frame _____	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>from</u>	Keelsons _____	Sails } <u>suft.</u>
Planksheers _____	Clamps and Shelves } <u>seen</u>	Anchors No. of _____
Sheerstrakes } <u>Caulked</u>	Ceiling _____	Cables _____
Topsides } <u>Caulked</u>	Rudder <u>Metal</u>	Hawsers and Warps _____
Wales _____	Copper _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	When put on <u>1833</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She appears to be fit for the safe conveyance of heavy
and perishable Cargoes, and to be continued as
Classed A. 1.

The Amount of Fee.....£ : : is received by me, P. Wynn

Special..... / : / :

Certificate (if required) : 5 :

Committee's Minute 7th September 1858

Character assigned A. 1.



© 2019

Lloyd's Register
Foundation

LON640-0154