

# REPORT of SURVEY for REPAIRS.

22127

No. 332 Survey held at London Date Oct 6<sup>th</sup> 5<sup>th</sup> 1858  
 on the Brig "Spherrid" Master R. Spragge  
 Tonnage 270 Built at Bermuda When built 1826  
 By whom built \_\_\_\_\_ Owners Chas<sup>r</sup> Scrutton &  
 Port belonging to London Destined Voyage S<sup>t</sup>. Vincent  
 If Surveyed Afloat or in Dry Dock Limitila Ship & West India Dock.

Last Survey, No. 20865 Port London Classed \* A. 1 S.S. 57

## REPAIRS

Now done the upper deck renewed with Dantzic deal. 3-  
 one piece of waterway on the starboard bow with Dantzic  
 oak - One Hold Beam end new with Teak, and three beams  
 strengthened with Iron plates. the upper deck wood  
 lodging knees additionally bolted.

She has had fifteen fathoms of Chain Cable replaced,  
 by short Stud 1 1/2 -

## Present Condition of the

Decks <u>new Caulked</u>	Treenails	Windlass and Capstan
Waterways <u>part new, good</u>	Breasthooks and Stemson	Pumps
Comings <u>good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder <u>Yellow Metal</u>	Hawsers and Warps
Wales	<u>Copper</u> When put on <u>1836</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She now appears to be in efficient Condition, fit in my opinion  
 for the safe Conveyance of dry and perishable Cargoes to  
 and from all parts of the world and to remain classed

The Amount of Fee.....£ - : 10 : - is received by me, B. W. W. W. W.

Special..... 1 : 1 : -

Certificate (if required) : : -

Committee's Minute 15<sup>th</sup> October 1858

Character assigned \* A. 1 Asterisk



© 2019

Lloyd's Register  
Foundation

CON640-0214