

REPORT of SURVEY for REPAIRS.

22226

Rev. 11.2.59

No. 42 Survey held at London Date Feb. 9th 185 9
 on the Ship "Earl of Hardwicke" Master Noakes
 Tonnage 903 Built at London When built 1838
 By whom built 961 Owners P. Green
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Messrs Greens' Upper Dry Dock

Last Survey, No. 21536 Port London Classed Rest-36-S.D.-1. ¹²

REPAIRS Now done, the Yellow Metal sheathing stripped off the bottom, the doubling continued from the upper turn of the bilge to the keel with 3^{ins} Dantzic deal and Spruce on felt after the bottom was caulked. five strakes of thin Ceiling each side, excepting the fore and after shifts replaced by 4 Dantzic Oak, defective chocks exposed renewed and a few fillings introduced, part new timber strake and three ceiling planks new - Ten pairs of bilge Iron Riggers introduced extending from the short floor Heads 15 feet in length, bolted with 1¹/₂ G. Metal bolts - The keel hung in shores and caulked from the keel to the waterways and part of the deck, her bottom sheathed with G. Metal.

Present Condition of the

Decks <u>part caulked</u>	Treenails <u>part new</u>	Riding Bits
Waterways <u>caulked</u>	Breasthooks and Stems	Windlass and Capstan
Comings <u>good</u>	Transoms, Pointers, and Crutches	Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame	Boats
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons	Masts, Yards, &c.
Planksheers	Clamps and Shelves	Sails
Sheerstrakes } <u>caulked</u>	Ceiling <u>part new</u>	Anchors No. of } <u>Good and</u>
Topsides	Rudder <u>G. Metal</u>	Cables
Wales	Copper	Hawsers and Warps
Plank (Bottom) and Counter <u>caulked</u>	When put on <u>now</u>	Standing & Running Rigging <u>refitted</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now fit in our opinion to remain as classed -
Restored S.D.-1.

The Amount of Fee.....£ 2 : - : - is received by me,

Special.....2 : 2 : -

Certificate (if required) : 5 : -

Committee's Minute 22nd February, 185 9

Character assigned Rest-36-S.D.-1 record repairs
Charge £2.2 for extra attendance



© 2019

Lloyd's Register Foundation

LN640-0402