

REPORT of SURVEY for REPAIRS.

No. ⁴⁵² Survey held at London Date Feb 25th Mar 1859
 on the Ship Lucknow Master Asplett
 Tonnage 641 Built at Anduld When built 1850
 By whom built _____ Owners P Pellier
 Port belonging to Jersey Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In Lavender Bay Dock

Last Survey, No. 1322 Port Sunderland Classed 10 A 1
2 No 50

REPAIRS*now done -*

*Docked to examine Bottom. Caulked from
 yellow Metal Sheathing upwards.*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <i>Good</i>	Breasthooks and Stemson } <i>Good where seen</i>	Pumps
Comings } <i>Good</i>	Transoms, Pointers, and Crutches } <i>Good where seen</i>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <i>In good order and sufficient</i>
Lower Deck Beams & Fastenings } <i>d⁴ where seen</i>	Keelsons <i>d⁴</i>	Sails <i>where seen</i>
Planksheers	Clamps and Shelves <i>d⁴</i>	Anchors No. of <i>3 - K 2</i>
Sheerstrakes <i>d⁴</i>	Ceiling <i>d⁴</i>	Cables
Topsides <i>d⁴</i>	Rudder <i>d⁴</i>	Hawsers and Warps
Wales <i>d⁴</i>	Copper <i>Yellow Metal</i> When put on <i>50</i>	Standing & Funning Rigging
Plank (Bottom) and Counter <i>d⁴</i>	Caulking of Bottom, Deck, & Waterways. <i>Good where tried</i>	

General Observations and Opinion,

*She appears to be in good condition, eligible to
 remain as Classed A 1*

The Amount of Fee.....£ : : is received by me,

For fee extra Special..... 1 : 1 : 0
attention on Certificate (if required) : 5 : -

Committee's Minute 14th March 1859Character assigned 10 A 1

© 2019

Lloyd's Register
Foundation

LON640-0444