

22799

## REPORT of SURVEY for REPAIRS.

No. 349 Survey held at London Date 28<sup>th</sup> Oct & 1<sup>st</sup> Nov 1858  
 on the 13<sup>th</sup> "Lochnagar" Master Seukins  
 Tonnage 380 Built at Sunderland When built 1847  
 By whom built \_\_\_\_\_ Owners Parke & Co  
 Port belonging to Traraburgh Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Nelson patent Slip

Recd 22.11.58  
Cat

Last Survey, No. 13797 Port Spool Classed G A 1  
 cont 56 - 3 yrs

## REPAIRS

Yellow metal patches where required, caulked from Yellow Metal line over all, some bolts to lower deck lodging knees driven out and renewed and a few Treennails in bilges fore and aft caulked of buttocks and other parts above Metal line and found it satisfactory  
 she has new Fore and Main Topsail Yards

## Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan <u>with P.P. which, Good</u>	
Waterways		Breasthooks and Stemson		Pumps <u>2 of Iron</u>	<u>do</u>
Comings		Transoms, Pointers, and Crutches		Boats <u>three</u>	<u>do</u>
Upper Deck Beams & Fastenings	} <u>where</u>	Timbers of the Frame	} <u>where</u>	Masts, Yards, &c. <u>do</u>	
Lower Deck Beams & Fastenings		Keelsons		Sails <u>do</u>	
Planksheers		Clamps and Shelves		Anchors No. of <u>3 13. 15 &amp; 16</u>	
Sheerstrakes	} <u>seen</u>	Ceiling	} <u>In good order and sufficient</u>	Cables	
Topsides		Rudder <u>Yellow metal on felt</u>		Hawsers and Warps	
Wales		Copper <u>When put on 1836</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This vessel appearing at present in good condition we are of opinion she may continue as classed A 1

The Amount of Fee.....£ - : - : is received by me,

Special..... 1 : 1 : - 12/1/59

Certificate (if required) : :

Committee's Minute 6<sup>th</sup> December 1859Character assigned Deferred

Will m. C. Davey

J. D. Martin



© 2019

Lloyd's Register  
Foundation

LON 642-0018