

# REPORT of SURVEY for REPAIRS.

No. 311 on the S. "Sea Star" Survey held at London Date 27<sup>th</sup> Mar 1860  
 Master Louitt 2<sup>nd</sup> APL  
 Tonnage 654 Built at Aberdeen When built 1855  
 By whom built W & L Hall Owners Livingstone &  
 Port belonging to Glasgow Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Rep<sup>d</sup> Green's dry dock

Last Survey, No. 22029 Port London Classed 9A1

## REPAIRS

Through damage sustained for full particulars see Special Report thereon -

Yellow metal stripped off, hung in shores, recaulked from keel to gunwale - 106 ft of false keel renewed & encased on feet -

Not of damage - Rider keelson except after piece renewed with Pitch pine - decks & Waterways recaulked -

## Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
X Upper Deck Beams & Fastenings	Iron	Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper		Standing & Running Rigging	
Plank (Bottom) and Counter		When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

This vessel being at present in good condition we are of opinion she may continue as classed 9A1

The Amount of Fee.....£ 7 : 7 : 7 is received by me,  
 Special Attendance 3 : 3 : 1  
 damage  
 Certificate (if required) : 5 : -

Committee's Minute 20<sup>th</sup> April 1860

Character assigned 9A1

Will: C. Dacey

© 2019

Lloyd's Register Foundation

LON 642-0314