

REPORT of SURVEY for REPAIRS.

23363

No. 150 Survey held at London Date August 13th 18 60
 on the "Laughing Water" Master Jane
 Tonnage 491 Built at Colchester When built 1856
 By whom built _____ Owners Mills Bawtry
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock New Crane dry dock

Last Survey, No. 156941 Port Liverpool Classed 4 A 1
 59

REPAIRS

This vessel was placed under survey for Continuation on opening her at the bilges (partial) sixteen first futtocks of English Oak and fourteen of English Elm on the port and eleven of oak and nine of Elm on the Starboard side were found very defective on which the owner declined any repairs for classification

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

In consequence of the defective condition of the frame as above stated we are of opinion this vessel is not eligible to remain clasped in the Register Book

The Amount of Fee.....£ : : is received by me,

Special..... / : / :

Certificate (if required) : :

Committee's Minute 14th August 18 60

Character assigned Expense Character

Jos. W. Warton
 W. S. Munford

Notice to Owners
 14/8/60



© 2019

Lloyd's Register Foundation

Lon 643-0131