

REPORT of SURVEY for REPAIRS.

23373

No. ³⁵ Survey held at London Date 17th August 1860
 on the Brig "Narcissus" Master Qualey
 Tonnage 107 Built at Carbis When built 1836
 By whom built _____ Owners Tindalls
 Port belonging to Carbis Destined Voyage Lon.
 If Surveyed Afloat or in Dry Dock Jeff^r Tindalls dock ways

Last Survey, No. 1853 Port Hockton Classed 11th A. 38
SS 32

REPAIRS

The planks next the waterways on each side renewed. The keelson cleared & examined.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>and</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>sufficient</u>
Planksheers <u>Good where seen</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>where</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>seen</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This Vessel is in good and efficient condition fit for the safe conveyance of dry and perishable cargoes for short voyages and eligible to be classed

The Amount of Fee.....£ 10 : — is received by me, A. S.

Special..... : :

Certificate (if required) : :

Committee's Minute 17th August 1860

Character assigned A. 1



© 2019

Lloyd's Register Foundation

LON 643-0140