

23385

change of owners

# REPORT of SURVEY for REPAIRS.

No. 178 Survey held at London Date July 14<sup>th</sup> 18 60  
on the Br. Perquimac Oliver Master J. W. Doyle  
Tonnage 409 Built at Sunderland When built 1853  
By whom built \_\_\_\_\_ Owners W. P. Poshonier &  
Port belonging to London Destined Voyage Alexandria  
If Surveyed Afloat or in Dry Dock Afloat at St. Katharines dock

Last Survey, No. 21721 Port London Classed S. A. 1  
58

## REPAIRS

### Present Condition of the

Decks	} <i>good</i>	Treenails	} <i>good</i>	Windlass and Capstan	} <i>good</i>	
Waterways		Breasthooks and Stemson		Pumps		
Comings		Transoms, Pointers, and Crutches		Boats		
Upper Deck Beams & Fastenings	} <i>do</i>	Timbers of the Frame	} <i>where seen</i>	Masts, Yards, &c.	} <i>good and</i>	
Lower Deck Beams & Fastenings		Keelsons		Sails		} <i>sufficient</i>
Planksheers		Clamps and Shelves		Anchors No. of		
Sheerstrakes		Ceiling		Cables		
Topsides		Rudder		Hawsers and Warps		
Wales	} <i>where seen</i>	Copper <i>12 1/2</i> When put on <i>1858</i>	Standing & Running Rigging			
Plank (Bottom) and Counter						

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

*This vessel appears in good condition and is eligible in my opinion to remain classed A 1*  
*Wm. H. Wain*

The Amount of Fee.....£ 1 : 0 : 0 is received by me,

Special..... : : 38

Certificate (if required) : 5 : 0

Committee's Minute 26<sup>th</sup> August 18 60

Character assigned S. A. 1

