

23402

REPORT of SURVEY for REPAIRS.

No. 641 Survey held at London Date 11th to 20 Aug^r 1860
on the B^d. "Emperor" Master Dennis ~~Thorn~~
Tonnage 264 Built at Aberdeen When built 1849
By whom built 200 Owners Dennis ~~Thorn~~
Port belonging to Aberdeen Destined Voyage Archangel
If Surveyed Afloat or in Dry Dock Globe dry dock

Recd 24.9.60

Last Survey, No. 22712 Port London Classed G.A.1
Count 88 - 3 59

REPAIRS

Yellow metal stripped off, recaulked from keel to beam next waterways, 2 planks of deck next the waterway on each side renewed to make good waterway seam 2 long and one short buttock plank on the Starboard side renewed (through defect) with Baltic Oak, also one topside plank on each side new of Pitch pine - new caulking tested and pieces cut out where required to make seams good

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings	Good	Transoms, Pointers, and Crutches	Good	Boats	in good
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	where	Keelsons	where	Sails	
Planksheers		Clamps and Shelves		Anchors No. of	order and
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder	seen	Hawsers and Warps	in good
Wales	seen	Copper	None	Standing & Running Rigging	
Plank (Bottom) and Counter		When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

This vessel appears at present in good condition and in my opinion may continue as classed A1

Will ^m C. Davey

The Amount of Fee.....£ - : 10 : - is received by me,

Special Caution and attendance } 1 : 0 : -
Certificate (if required) : : -

Committee's Minute 4th September 1860

Character assigned Good

Recd 24.9.60
Expense 1/6

© 2019

Lloyd's Register Foundation

LN 643-0160