

# REPORT of SURVEY for REPAIRS.

23494

No. 23161 Survey held at London Date 17 Sept 1860  
 on the Ship "Herefordshire" Master Wm Escott  
 Tonnage 1354 Built at Bombay When built 1813  
 By whom built \_\_\_\_\_ Owners G Marshall  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock in East India Dock

Last Survey, No. 23161 Port London Classed \*A 1 in Red

## REPAIRS

Culm in hold repaired New Comings fitted  
 to Fore, Main, & after hatches. Run of head  
 repaired New tops, & Caps, to lower masts  
 new standing rigging fitted - Hull,  
 masts, & rigging, generally overhauled  
 and refitted

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>overhauled</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>well</u>
Lower Deck Beams & Fastenings <u>firm</u>	Keelsons <u>good</u>	Sails <u>found</u>
Planksheers <u>x</u>	Clamps and Shelves	Anchors No. of <u>x</u>
Sheerstrakes <u>good</u>	Ceiling	Cables <u>sufficient</u>
Topsides	Rudder	Hawsers and Warps <u>new</u>
Wales	Copper <u>up</u> When put on <u>1860</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

## General Observations and Opinion,

## Caulking of Bottom, Deck, & Waterways.

This Vessel is fit for the safe conveyance  
 of dry & perishable Cargoes to & from all  
 Ports of the world and is eligible to be manned

The Amount of Fee.....£ / : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 19<sup>th</sup> October 1860

Character assigned A 1 asterisk

as Classed  
\*A 1 in Red  
J. H. Ritchie



Lloyd's Register  
 Foundation

LON 043 - 0 248