

REPORT of SURVEY for REPAIRS.

23539

No. 227 Survey held at London Date Oct 11th to 18th 1880
 on the Brig "Florist" Master L. S. Allen
 Tonnage 273 Built at Sunderland When built 1831
 By whom built _____ Owners Ships^{rs} Gray &
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Ships^{rs} Youngs' Dry Dock

Last Survey, No. 21325 Port London Classed 8 Δ Capred

REPAIRS Now done, she has been scraped bright extending from the light-water mark to the waterway stem several treenails and some bolts driven out for survey, and all the other preliminary requirements for continuation attended to.

The following renewed - viz - A stroke of deck each side next the waterway, the four pieces of Stag Kelson, one starboard blank in the wales and five short pieces of them with Pitch Pine, the trenails extending from the Gunwale to the bilges Caulked and all those which were found defective renewed - she has been hung in shores and Caulked from the Keel to the Gunwale, and her bottom resheathed with Yellow Metal on Fell.

Several Planks in the wale, buttock, and upper course of bottom which proved defective have not been removed as recommended, there were also two starboard and one

Present Condition of the starboard beam end defective -

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>suff^r</u>
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder <u>Yellow Metal</u>	Hawsers and Warps
Wales	<u>Copper on Fell</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>hung in shores</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. not tested -

We recommended several defective planks, the whole of the trenails extending from the Gunwale to the bilges and three beam ends to be renewed, the Captain, on behalf of the Owner declined to comply, or to proceed for classification -

The Amount of Fee.....£ : : is received by me,

Special.....2 : 2 :

Certificate (if required) : :

Committee's Minute 9th November 1880

Character assigned Record date of Survey



Lloyd's Register Foundation

LON 643 - 0284