

23590

REPORT of SURVEY for REPAIRS.

No. 330 on the Bk "Sebastian" Survey held at London Date 12th to 14th Nov 1860
Master R. Begg
Tonnage 426 Built at Sunderland When built 1855
By whom built _____ Owners Voyce &
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Nelson Patent Slip

Rev. 12.60

Last Survey, No. 22420 Port London Classed Y A 1
57

REPAIRS

Yellow metal stripped off hull in threes and a false
keel added 15 iron bolts on each side in knees & Breasthook
fore side of fore mast taken out and renewed with Copper
iron built bolts under metal line punched up and metal
new added, caulked from keel to gunwale and the bottom
renewed on feet
new main mast

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1860</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

This vessel being at present in good condition
we are of opinion she is eligible to continue as classed

The Amount of Fee.....£ : : is received by me,

Special Clerk: / : / : -

Certificate (if required) : :

Committee's Minute 4th December 1860

Character assigned Y A 1

Will. L. Davey
J. Martin



© 2019

Lloyd's Register
Foundation

W0643-0334