

* 23741

REPORT of SURVEY for REPAIRS.

Change of Owners

No. _____ Survey held at London Date Oct^r 31st 1861
on the Ship "Albion" Master Robertson
Tonnage 869 Built at London When built 1839
By whom built _____ Owners W. MacKinnon
Port belonging to Glasgow Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Wipac's Dry Dock & Co. J. dock.

Last Survey, No. 23360 Port London Classed Per 155 for 8 yrs.

REPAIRS now done, yellow-metal patched. Caulked from metal upwards, two after pieces of false rail and one fore piece renewed of elm.

Present Condition of the

Decks <u>good</u>	Treenails _____	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson _____	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches _____	Boats <u>good and sufficient</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where seen</u>	Sails _____
Planksheers <u>"</u>	Clamps and Shelves <u>seen</u>	Anchors No. of _____
Sheerstrakes <u>caulked</u>	Ceiling _____	Cables _____
Topsides <u>"</u>	Rudder _____	Hawsers and Warps <u>one new of 5 1/2</u>
Wales <u>"</u>	Copper <u>new</u> When put on <u>1859</u>	Standing & Running Rigging <u>seen</u>
Plank (Bottom) and Counter <u>good where seen</u>	Caulking of Bottom, Deck, & Waterways. <u>good where seen.</u>	

General Observations and Opinion,

This vessel is now in my opinion eligible to remain as Classed A1.

The Amount of Fee.....£ : : is received by me,

Special..... : :


Certificate (if required) : :

Committee's Minute 18

Character assigned

Charge for attendance £1.2.0

J. F. Light.



© 2021

Lloyd's Register Foundation

LON644-0037