

24050

REPORT of SURVEY for REPAIRS.

No. 120 Survey held at London Date 13th July to 27th Aug 1869
on the S. "Harrowby" Master Storie
Tonnage 574 73 Built at New Brunswick When built 1853
By whom built _____ Owners Stinnair
Port belonging to London Destined Voyage Hobart Town
If Surveyed Afloat or in Dry Dock Globe dry dock & London dock

Last Survey, No. 21874 Port London Classed Y.A.1

REPAIRS

Yellow metal stripped off recaulked from keel to metal line and remetalled on feet -
Midlass stripped of its linings and main piece found defective now renewed with English Oak
New Caulking tested and found satisfactory

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	with <u>new</u>	} <u>Good</u>
Waterways		Breasthooks and Stemson		Windlass and Capstan	
Comings		Transoms, Pointers, and Crutches		Pumps <u>2 of wood</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame		Boats <u>3 do</u>	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Masts, Yards, &c.	} <u>do</u>
Planksheers		Clamps and Shells		Sails	
Sheerstrakes		Ceiling		Anchors No. of <u>3 B. 15 & 1 K</u>	
Topsides		Rudder		Cables <u>complete</u>	
Wales	} <u>seen</u>	Copper <u>Iron on feet</u>	} <u>seen</u>	Hawsers and Warps <u>(new) supp</u>	} <u>good</u>
Plank (Bottom) and Counter		When put on <u>1860</u>		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

This ship is now in good condition and eligible in my opinion to continue as Classed A1

Will: L. Davey

The Amount of Fee.....£ : : is received by me,

Special Caulk. 1 : 1 : - 16/4/61

Certificate (if required) : :

Committee's Minute 19th July 1869

Character assigned Record Yell.



© 2021

Lloyd's Register
Foundation

LON644-0302