

24652

REPORT of SURVEY for REPAIRS.

No. ⁴⁸⁵ on the S. "Syburaia" Survey held at London Date 5th to 26th April 1862
Tonnage 1027 Built at Glasgow Master S. Coote
By whom built 962 Owners Somes Bw.
Port belonging to London Destined Voyage Bombay

If Surveyed Afloat or in Dry Dock Rep^d Somes dry Dock East India Dock

Last Survey, No. 23309 Port London Classed 14-A
60

REPAIRS
Yellow metal stripped off, recaulked from keel to the gunwale and remetalled on felt, new caulking where tested found satisfactory. New mast steps. Ripping overhauled and refitted

Present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y.M.S.</u> When put on <u>how done</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where tested
This ship is now in good condition and in my opinion eligible to continue as classed A1

The Amount of Fee.....£..... is received by me,
Special Clerk. 1: 1: -

Certificate (if required)
Committee's Minute 13th May 1862
Character assigned 14-A

Will^m L. Davy