

24744

Change of Owners &c
REPORT of SURVEY for REPAIRS.

Nov 28/62

No. 91 Survey held at London Date June 2nd 1862 1862
on the Barque "General Hancock" Master Stephen Spowart
Tonnage 331 Built at Sunderland When built 1838
By whom built _____ Owners J. Patton
Port belonging to London Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock Bull Head Quay Dock & London Dock.
Last Survey, No. 23831 Port London Classed 10A-1
61

REPAIRS
Now done, the bottom Caulked and sheathed with yellow metal on felt; the Caulking tested and found good; the Fore Mast and the Mizzen Mast both shipped forward -

Present Condition of the

Decks	} Good where seen	Treenails	} Good where seen	Windlass and Capstan	} Good and sufficient
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} Firm	Timbers of the Frame	} Good	Masts, Yards, &c.	} Good and sufficient
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers	} Good where seen	Clamps and Shelves	} Good	Anchors No. of	} Good and sufficient
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	Yellow metal	Standing & Running Rigging			
Plank (Bottom) and Counter	Copper on felt	When put on how			

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where tested -
She is now in good and efficient Condition. fit in my opinion to remain as classed - 10A-1.
J. W. Weymouth

The Amount of Fee..... £ 1 : 0 : 0 is received by me,
Special..... 1 : 1 : 0
Certificate (if required)..... 5 : 0 : 0

Committee's Minute 24th June 1862
Character assigned 10A-1
record 444

