

25154
Nov 26. 12. 62
End

REPORT of SURVEY for REPAIRS.

No. 24 Survey held at London Date Nov 11th 18 62
On the M^{rs} Harmony Master H. Pinklaton
Tonnage 257 Built at Fellows When built 1861
By whom built Fellows Owners L. Spence
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Gun dry dock

Last Survey, No. 24677 Port London Classed 13 A 1
62

REPAIRS

Caulked keel to metal line and sheathed with
line on Paper X

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	Good & sufficient
Lower Deck Beams & Fastenings	Good	Keelsons	Good	Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>Iron</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good condition and is eligible
in my opinion to remain classed 13 A 1

Thos. W. Brown

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 :

Certificate (if required) : :

Committee's Minute 23rd January 18 63

Character assigned 13 A 1

revised 4th June



© 2019

Lloyd's Register
Foundation

Lon 646-0326