

25166

# REPORT of SURVEY for REPAIRS.

No. 222 Survey held at London Date June 7<sup>th</sup> 18 62  
on the S Akbar Master J. Pizze  
Tonnage 218 Built at Sunderland When built 1851  
By whom built \_\_\_\_\_ Owners Luscombe  
Port belonging to London Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock Linthouse dry dock & W I Dock

Last Survey, No. 22513 Port London Classed 13 A 1  
61

## REPAIRS

The yellow metal repaired and the ship recaulked from metal line to plank sheers —

### Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame	<u>Good</u>	Masts, Yards, &c.	<u>In good order</u>
Lower Deck Beams & Fastenings	<u>where</u>	Keelsons	<u>where</u>	Sails	<u>and</u>
Plank sheers	<u>seen</u>	Clamps and Shelves	<u>seen</u>	Anchors No. of	<u>sufficient</u>
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>L &amp; Y M</u>	When put on <u>1861</u>	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in a good and efficient state of repair and is eligible in my opinion to remain classed

13 A 1

The Amount of Fee.....£ \_\_\_\_\_ is received by me,

Special..... 1 : 1 : - B

Certificate (if required) : :

Jos. W. Wain

Committee's Minute 27<sup>th</sup> January 18 63

Character assigned 13 A 1



© 2019

Lloyd's Register Foundation

LON 646-0335