

25235

Change of Owners &
REPORT of SURVEY for REPAIRS.

No. 290 Survey held at London Date Jan 2nd to Feb 11th 1863
on the Ship "Lincelles" Master Heightholm
Tonnage 904 Built at Broulmein When built 1858
By whom built _____ Owners Sup^t J^r Allan
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Sup^t Wigram's Day Dock & E. J. Dock

Last Survey, No. 24523 Port London Classed 13A.1.
61

REPAIRS

Now done, the yellow metal sheathing stripped off the bottom; the wood sheathing carefully spiled, Caulked, additionally fastened, coated with two coats of half pitch and tar, felted with the best felt which was then coated with tar and sheathed with yellow metal -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Yellow metal	Standing & Running Rigging
Plank (Bottom) and Counter	Copper on felt	
General Observations and Opinion,	and wood sheathing	
	Caulking of Bottom, Deck, & Waterways.	

She is a good, firm ship - fit in my opinion to remain as classed 13A.1.

B. Weymouth

The Amount of Fee.....£ 1 : : is received by me, *[Signature]*

Special..... : : :

Certificate (if required) : : :

Committee's Minute 24th February 1863 -

Character assigned 13A.1 record *[Signature]*



© 2019
Lloyd's Register
Foundation
LON 646-0393