

# ANNUAL SURVEYS.

25250

No. 109 Survey held at London Date Febr<sup>y</sup> 19<sup>th</sup> 1863  
on the Ship Mangerton Master Wm Penney  
Tonnage 993 Built at Quebec When built 1859  
By whom built                      Owners G. Sweeting  
Port belonging to London Destined Voyage                       
If Surveyed Afloat or in Dry Dock Clyde dry dock & afloat

Last Survey, No. 23817 Port of London Classed S.S. 59<sup>th</sup> 1<sup>st</sup> in red  
SS 59-5<sup>th</sup> in red  
Dec 63

The present Condition of the

Decks <u>in good order</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>new main piece</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Wood Sheath</u> When put on <u>1859</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

At this date stripped off the whole of the yellow metal sheathing, and a portion of the wood sheathing, at the fore end on each side and caulked the seams. - Renewed a portion of the wood sheathing forward and refitted two of the raft ports, lifted the Rudder and introduced a new main piece, also a few short lengths of ceiling in the lower hold forward. - This vessel being now in good condition Committee's Minute 3<sup>rd</sup> March 1863. I am of opinion: She is eligible to remain as

Character assigned

1 in red

Class'd 4. A. 1 in red

Samuel Previous

Certificate (if required)

No. 116 Survey held at London Date Feb<sup>y</sup> 21<sup>st</sup> 1863  
on the Barque Sanarkshvie Master W. Western  
Tonnage 629 Built at                      When built 1840  
By whom built                      Owners Whitwell &  
Port belonging to Bristol Destined Voyage                       
If Surveyed Afloat or in Dry Dock Clyde dry dock

Last Survey, No. 2520 Port of Bristol Classed S. A. 1 SS 60-4<sup>th</sup>  
C 2 61

The present Condition of the

Decks <u>                    </u>	Treenails <u>                    </u>	Windlass and Capstan <u>                    </u>
Waterways <u>                    </u>	Breasthooks and Stemson <u>                    </u>	Pumps <u>                    </u>
Comings <u>                    </u>	Transoms, Pointers, and Crutches <u>                    </u>	Boats <u>                    </u>
Upper Deck Beams & Fastenings <u>                    </u>	Timbers of the Frame <u>                    </u>	Masts, Yards, &c. <u>                    </u>
Lower Deck Beams & Fastenings <u>                    </u>	Keelsons <u>                    </u>	Sails <u>                    </u>
Planksheers <u>                    </u>	Clamps and Shelves <u>                    </u>	Anchors No. of <u>                    </u>
Sheerstrakes <u>                    </u>	Ceiling <u>                    </u>	Cables <u>                    </u>
Topsides <u>                    </u>	Rudder <u>                    </u>	Hawsers and Warps <u>                    </u>
Wales <u>                    </u>	Copper <u>                    </u> When put on <u>                    </u>	Standing & Running Rigging <u>                    </u>
Plank (Bottom) and Counter <u>                    </u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways                     

At the request of the Owners Survey'd this Barque for damage but in respect to surveying her with a view to reporting for class they stated to me that for the present they must decline it. I am therefore of opinion Committee's Minute 3<sup>rd</sup> March 1863. She is ineligible to retain her present character

Character assigned

Expence Character

Notice to Owners  
3/3/63

Samuel Previous

Certificate (if required).

LON 646 0406