

25293

Recd 18/3/63

REPORT of SURVEY for REPAIRS.

No. 2 Survey held at London Date Jan^y 24th 18 63
on the S. "Nimrod" Master R. S. Stuart
Tonnage 893 Built at Sunderland When built 1853
By whom built _____ Owners J Allan & Co
Port belonging to London Destined Voyage Madras
If Surveyed Afloat or in Dry Dock Limetown dry dock

Last Survey, No. 24212 Port London Classed 13 A 1
10.61

REPAIRS

Yellow-metal stripped recaulked from keel to metal line and the yellow metal sheathing renewed on Felt

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	<u>Good &</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Do Do at other places		Sails	<u>sufficient</u>
Planksheers	<u>where</u>	Keelsons	<u>Good</u>	Anchors No. of	
Sheerstrakes	<u>seen</u>	Clamps and Shelves	<u>where seen</u>	Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>1 1/2</u> When put on <u>now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good condition and is eligible in my opinion to remain classed 13 A 1

The Amount of Fee.....£..... is received by me,

Special..... 1: 1: - SS

Certificate (if required) : :

Thos. W. Hawn

Committee's Minute 20th March 18 63

Character assigned 13 A 1 W. H. Hawn