

REPORT of SURVEY for REPAIRS.

No. 12 Survey held at London Date Nov 6 to 17 1862
 on the Ship "Kent" Master Clayton
 Tonnage 879 Built at London When built 1833
 By whom built 998 Owners Messrs Wigram
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Wigram's Dry Dock & E. J. Scott

Last Survey, No. 24438 Port London Classed 13A.1.
62

REPAIRS

*Now done, hung in shores and Caulked throughout
 her bottom sheathed with yellow metal on felt.*

Present Condition of the

Decks	} <u>Caulked</u>	Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings	<u>Good</u>	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>Good</u>	Timbers of the Frame	} <u>Good where seen</u>	Masts, Yards, &c.	} <u>Good and Sufficient</u>
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides	} <u>Caulked</u>	Rudder		Hawsers and Warps	
Wales		<u>Yellow Metal</u>		Standing & Running Rigging	
Plank (Bottom) and Counter	<u>Caulked</u>	Copper <u>on Felt</u> When put on <u>Now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested.

She is now in good and efficient Condition, fit in my opinion to remain as classed 13A.1.

B. W. Weymouth

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required) : : -

Committee's Minute 27th March 1863

Character assigned 13A.1 *Good*

Charge £1.1.0



© 2021

Lloyd's Register
 Foundation

LN 647-0020