

25450
Recd 25/5/63

REPORT of SURVEY for REPAIRS.

No. 65 Survey held at London Date April 24 & 27 18 63
on the Ship Dartmouth Master Davis
Tonnage 933 Built at Dundee When built 1839
By whom built Owners Messrs Somers Bros
Port belonging to London Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 24868 Port London. Classed 14th 1st 7.62

REPAIRS Now done, the Yellow Metal renewed on Telt, and her bottom Caulked to the Metal line -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } Good	Breasthooks and Stemson	Pumps
Comings }	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame } Good	Masts, Yards, &c. } Good and
Lower Deck Beams & Fastenings } Good	Keelsons	Sails } sufficient
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes }	Ceiling	Cables
Topsides } Good	Rudder	Hawsers and Warps
Wales }	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter } Caulked	Copper on Telt When put on Now	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good when tested.
She is now in good and efficient Condition, fit in my opinion to remain as classed 14th 1st
B. T. Weymouth

The Amount of Fee.....£ : : is received by me,
Special..... / : / :
Certificate (if required) : :

Committee's Minute 26th May 18 63.

Character assigned 14th 1st record