

25453

REPORT of SURVEY for REPAIRS.

No. 249 Survey held at London Date May 5th 1863
on the Ship "Isles of the South" Master W. Haines
Tonnage 821 Built at Lunderland When built 1859
By whom built _____ Owners Cox & Co
Port belonging to London Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Migram's Dry Dock

Last Survey, No. 2499 Port London Classified 13. A. 1.
61

REPAIRS now done.

Yellow metal sheathing stripped, the butts of the bottom planking, hood ends and keel seam recaulked; resheathed with copper on paper and the topsides caulked

Present Condition of the

Decks	<u>good</u>	Treenails	<u>good</u>	Windlass and Capstan	<u>good &</u>
Waterways	<u>where</u>	Breasthooks and Stemson	<u>where</u>	Pumps	<u>sufficient</u>
Comings	<u>seen</u>	Transoms, Pointers, and Crutches	<u>seen</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>seen</u>	Timbers of the Frame	<u>seen</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>seen</u>	Keelsons	<u>seen</u>	Sails	<u>"</u>
Planksheers	<u>seen</u>	Clamps and Shelves	<u>seen</u>	Anchors No. of	<u>"</u>
Sheerstrakes	<u>seen</u>	Ceiling	<u>seen</u>	Cables	<u>"</u>
Topsides	<u>seen</u>	Rudder	<u>seen</u>	Hawsers and Warps	<u>"</u>
Wales	<u>seen</u>	Copper <u>on Paper</u> When put on <u>now</u>		Standing & Running Rigging	<u>"</u>
Plank (Bottom) and Counter	<u>seen</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

The ship is now in good & efficient condition and eligible in my opinion to remain as claped.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 5 : -

Committee's Minute 29th May 18 63

Character assigned 13 A 1

record collector



© 2021

Lloyd's Register
Foundation

LON647 0149