

25675

REPORT of SURVEY for REPAIRS.

No. 68 Survey held at London Date Aug 19th - 22nd 1863
on the Ship "Saladin" Master J. Baillie.
Tonnage 782 Built at Sunderland When built 1851
By whom built per Memo. 6.10.63 Owners Messrs Henderson
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock King & Queen Dry Dock
Last Survey, No. *24924 Port London. Classed 13 A.1.
62

REPAIRS

Now done

Sheathed with Yellow
Metal on Felt and Caulked
from Keel to gunwale —

Present Condition of the

Decks	} good	Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches	good	Boats	good
Upper Deck Beams & Fastenings		Timbers of the Frame	at the Openings	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Do Do	at other places		and
Planksheers		Keelsons	where	Sails	
Sheerstrakes		Clamps and Shelves	seen	Anchors No. of	Sufficient
Topsides	} caulked	Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Yellow Metal on Felt	When put on	Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where tested

She is now in our opinion fit for the
Conveyance of dry and perishable
goods, to and from all parts of the
World, and to remain as classed

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required) : :

Committee's Minute 8th September 1863

Character assigned 13 A.1

Charge £1-1-